

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Import Vehicles

CAMPAIGN NO.	4426	DATE	January 29 ,2019
MANUFACTURER		ISUZU MOTORS LIMITED	
DESCRIPTION OF DEFECT		Some of the brake pipes on the medium duty trucks are mounted in inappropriate positions that they might interfere with cross members. Therefore, these brake pipes might get damaged from incidents such as vibration while the trucks are in motion, resulting in a possible brake fluid leakage.	

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
2RG-FRS90S2	[FORWARD]	2017-2018	2
2PG-FSR90S2 2PG-FSR90T2 2RG-FSR90S2 2RG-FSR90T2		2017-2018	70
2RG-FSS90S2		2018	2
2PG-BSR90T2		2017-2018	2
		TOTAL	76