

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic / Import Vehicles

CAMPAIGN No.	4419	DATE	February 1. 2019
MANUFACTURER	YANMAR AGRIBUSINESS CO.,LTD.		
DESCRIPTION OF DEFECT	In the air intake hose to the turbocharger of agricultural combine harvester, the mounting structure is inappropriate, the hose may come off due to vibration. Therefore, if you continue to use it as it is, the output of the engine drops, and in the worst case the running speed may not come out.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
-	「AG6100R」	2014~2017	901
	「AG6114R」	2014~2017	524
	「AG7114R」	2014~2017	60
-	「YH6101」	2018	1
-	「YH6115」	2018	1
-	「YH590」	2015~2017	462
TOTAL			1,949