

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic / Import Vehicles

CAMPAIGN No.	4428	DATE	Feb. 1. 2019
MANUFACTURER	Hino Motors, Ltd.		
DESCRIPTION OF DEFECT	On certain heavy-duty sightseeing buses, due to the improper welding conditions of the rear spoiler fixing brackets, the welding strength may be inadequate. Therefore, by using it for a long term, the welding part may break, resulting the rear spoiler to come off in the worst case.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
2TG-RU1ASDA	[HINO SELEGA]	2017~2018	173
2RG-RU1ESDA		2017~2018	138
2DG-RU2AHDA		2017~2018	49
2KG-RU2AHDA			
		TOTAL	360