

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Import Vehicles

CAMPAIGN NO.	4429	DATE	February 1 ,2019
MANUFACTURER		ISUZU MOTORS LIMITED	
DESCRIPTION OF DEFECT		On certain heavy-duty sightseeing buses, due to the improper welding conditions of the rear spoiler fixing brackets, the welding strength may be inadequate. Therefore, by using it for a long term, the welding part may break, resulting the rear spoiler to come off in the worst case.	

TYPE	COMMERCIAL NAME	MODELYEAR RECALLED	NUMBER OF VEHICLE
2TG-RU1ASDJ	[ISUZU GALA]	2017-2018	106
2RG-RU1ESDJ		2017-2018	65
2DG-RU2AHDJ 2KG-RU2AHDJ		2017-2018	26
		TOTAL	197