

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Import Vehicles

CAMPAIGN NO.	4437	DATE	February 7, 2019
MANUFACTURER		ISUZU MOTORS LIMITED	
DESCRIPTION OF DEFECT		As for the folding slope ramp installed at the foot of the middle entrance of the bus, the dimensions of the parts of the flip-up grab are incorrect. Therefore, some grab portions of the flip-up grabs keep sticking up when the user pulls up the grab portions, potentially causing passengers to trip over them and fall.	

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
QDG-LV290N1 QKG-LV290N1 QPG-LV290N1	[ERGA]	2015-2017	1,045
2DG-LV290N2 2KG-LV290N2 2PG-LV290N2 2TG-LV290N2		2017-2018	579
QDG-LV290Q1 QKG-LV290Q1 QPG-LV290Q1 QRG-LV290Q1		2015-2017	228
2KG-LV290Q2 2PG-LV290Q2 2TG-LV290Q2		2017-2018	142
SKG-LR290J2	[ERGA MIO]	2016-2017	298
2KG-LR290J3		2017-2018	208
2SG-HL2ANBD	[ISUZU ERGA]	2018	7
2SG-HL2ASBD		2018	1
		TOTAL	2,508