

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	4 4 4 3	DATE	Feb. 14. 2019
MANUFACTURER	N I S S A N		
DESCRIPTION OF DEFECT	<p>In a combination meter, due to inappropriate layout of the electric circuit for the fuel meter, the circuit board of meter might repeat thermal expansion by self-heating of the resistance and the heat of the lighting element in the meter, and the circuit may break. This can cause the fuel meter to indicate greater than the actual amount of the fuel in the fuel tank. In an extreme case, if the driver does not awake a shortage of the fuel, the engine may stall during the driving and can not be restarted.</p>		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLES
CBA-E51	ELGLAND	2 0 0 4	23, 687
CBA-NE51		~	15, 792
CBA-ME51		2 0 0 7	27, 282
CBA-MNE51			10, 743
PA-AHW41	C I V I L I A N		1, 515
PA-AVW41			720
PA-AJW41			362
PA-ACW41			40
		TOTAL	80, 141