

## VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic ~~Import Vehicles~~

|                       |  |      |           |
|-----------------------|--|------|-----------|
| CAMPAIGN No.          | Gai-2782   | DATE | 2019/2/14 |
| MANUFACTURE           | Daimler AG<br>(Japanese Importer : Mercedes-Benz Japan Co., Ltd. )   |      |           |
| DESCRIPTION OF DEFECT | <p>On certain V-Class vehicles (Platform 447) with OM651 electric failures on the exhaust gas temperature sensor may occur due to insufficient durability of the component itself. The failure would be saved in the engine control unit and the respective warning lamp (MIL) would be activated.</p> <p>If, in case of the failure, the exhaust gas recirculation would be deactivated, compliance with the legal exhaust gas emission limits may not be given. The engine protection function with power limitation could be activated accordingly.</p> <p>The customer does receive the activated MIL in the instrument cluster as warning signal.</p> |      |           |

| TYPE       | COMMERCIAL NAME | MODEL YEAR RECALLED | NUMBER OF VEHICLE |
|------------|-----------------|---------------------|-------------------|
| LDA-447811 | V220d           | 2016                | 6                 |
| LDA-447815 |                 |                     | 2                 |
|            |                 | TOTAL               | 8                 |