

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

~~Domestic~~ /Import Vehicles

CAMPAIGN No.	Gai-2777	DATE	15/February/2019
MANUFACTURER	Automobiles Volvo Car Corporation (Japanese Importer: Volvo Car Japan Limited)		
DESCRIPTION OF DEFECT	Cracks in the inner layer of the hose in combination with a pressurised system can in worst case scenario result in fuel leakage. The corrective action is to replace the hose on the fuel line.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
VOLVO	[V40]	2015-2016	51,400
	[V40CC]	2015-2016	15,372
	[S60]	2015-2016	9,113
	[S60C]	2016	548
	[V60]	2015-2016	23,945
	[V60CC]	2016	7,899
	[XC60]	2015-2016	44,699
	[V70]	2015-2016	23,149
	[XC70]	2015-2016	4,616
	[S80]	2015-2016	2,649
	[XC90]	2016	36,027
TOTAL			219,417