VEHICLE SAFETY/ POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicle

CAMPAIGN No.	4440	DATE	Feb.19,2019		
MANUFACTURER	TADANO LTD.				
DESCRIPTION OF DEFECT	On some wheel crane braking devices, as a result of inadequate brake piping fitting dimensions, there are cases of the joints not being adequately tightened due to inadequate fitting length. Therefore, with continued use in this condition, brake fluid may leak from the joint, and in the worst cases, result in decreased braking force.				

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLES
YDS-T014	TADANO 「GR-160N-4」	2017-2018	204
YDS-EW08	KOBELCO 「RK160-8」	2017-2018	10
		TOTAL	214