

VEHICLE SAFETY RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	4446	DATE	Feb.21, 2019
MANUFACTURER	SUZUKI MOTOR CORPORATION		
DESCRIPTION OF DEFECT	<p>Due to the insufficient control program of onboard communication controller (Gateway controller), the communication function of this controller may shut off and the controller fails to shift into the sleep mode, when the ignition switch is turned off. If this condition occurred, the trouble diagnosis tool may not read trouble codes. And also, because the standby current flows continuously to this controller even with the ignition switch off, the battery may become empty and the engine may not start, if left a car parked for several days without starting the engine.</p>		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLES
DAA-MK53S	SPACIA	2017~2018	38,134
DAA-MN71S	XBEE		9,152
DAA-MM53S	FLAIR WAGON	2018	2,201
		TOTAL	49,487