

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Import Vehicles

CAMPAIGN No.	4447	DATE	Feb 22nd, 2019
MANUFACTURER	KYOKUTO KAIHATSU KOGYO CO., LTD. 6-1-45, Koshienguchi, Nishinomiya-shi, Hyogo prefecture, Japan		
DESCRIPTION OF DEFECT	In the relief valve of the gear pump for discharging the cargo of the tank truck, the pressure in the pipe line during the discharging operation may become high because the processing of the valve is inappropriate. Therefore, the load may leak from the seam of the gear pump main body or the piping.		

MANUFACTURER'S NAME	TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
ISUZU	2KG-CVR60C	GIGA	2018	1
	2KG-CYE60CM	GIGA	2017-2018	4
	2KG-CYG60CM	GIGA	2017-2018	7
	2KG-CYL60C	GIGA	2018	4
	QKG-CYG60BM	GIGA	2017	2
	2RG-FTR90U2	FORWARD	2018	1
HINO	2KG-FJ2ABA	HINO RANGER	2018	1
	2KG-FN1AJA	HINO PROFIA	2017-2018	3
	2KG-FN1AJG	HINO PROFIA	2017-2018	3
	2PG-FN1AJA	HINO PROFIA	2018	4
	2PG-FN1AJG	HINO PROFIA	2018	5
	2KG-GC2ABA	HINO RANGER	2018	1
MITSUBISHI	2KG-FK62FZ	FUSO FIGHTER	2018	1
	2PG-FU74GY	FUSO SUPERGREAT	2018	1
	2PG-FU74GZ	FUSO FIGHTER	2017-2018	3
UD TRUCKS	2PG-CD5BA	QUON	2018	1
KYOKUTO	KL24-17LS3	KYOKUTO	2017	1
	KL24-47LS9	KYOKUTO	2018	2
	KL24-47SS8	KYOKUTO	2018	1
	KTT241	KYOKUTO	2018	1
	KTT241S	KYOKUTO	2017	1
	KTT241S1	KYOKUTO	2018	1
			TOTAL	49