

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic/Import Vehicles

CAMPAIGN No.	gai-2786	DATE	Feb. 22, 2019
MANUFACTURER	DUCATI MOTOR HOLDING SpA (Japanese Importer: DUCATI JAPAN Ltd.)		
DESCRIPTION OF DEFECT	<p>In the hydraulic clutch hose, since the study of the heat effect is insufficient, pressure in the hose may decrease due to the influence of heat from the engine or the like. Therefore, the stroke of the clutch increases, and in the worst case, the clutch operation may not be performed.</p> <p>The official Ducati dealer will replace the clutch hose with a countermeasure. This will be performed free of charge.</p>		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
2BL-DA01J	Panigale V4	2018-2019	99
2BL-DA01J	Panigale V4 S	2018-2019	243
2BL-DA01J	Panigale V4 Speciale	2018-2019	57
TOTAL			399