

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	4448	DATE	25 February 2019
MANUFACTURER	KUBOTA Corporation		
DESCRIPTION OF DEFECT	Improper programming for the engine fuel control system may make incorrect engine combustion. This causes carbon to adhere to the engine valves and valve may stick, posing damage of the engine.		
TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
XDN-C430	「ER470」	2014~2017	873
		TOTAL	873