

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	4449	DATE	25 February 2019
MANUFACTURER	KUBOTA Corporation		
DESCRIPTION OF DEFECT	There is a fuel hose which touches the drive belts or pulleys, etc. because a fixation method of fuel hose is improper. Therefore fuel hose is a risk that the fuel hose gets damaged and the fuel leaks.		
TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
XDN-C430	「ER470」	2014~2017	1,722
YDN-C434		2017~2018	
		TOTAL	1,722