

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No	4 4 5 3	DATE	Feb.28.2019
MANUFACTURER	N I S S A N		
DESCRIPTION OF DEFECT	<p>Regarding the rear right and center seatbelt, the seatbelt buckle with incorrect belt length was installed due to parts mis-feed in vehicle assembly line.</p> <p>Therefore, in this condition, the rear seat occupant protection performance might not be comply with Japanese regulation in the event of accident.</p>		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLES
DBF-VY12	NV150 AD	2019	13
		TOTAL	13