

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Import Vehicles

CAMPAIGN No.	GAI-2787	Date	February 28, 2019
MANUFACTURER	Volkswagen (Japanese Importer: Volkswagen Group Japan KK)		
DESCRIPTION OF DEFECT	In the parking brake device, there are installation work instruction is inappropriate, the looseness prevention nut is not mounting to the connection between the brake lever and the brake cable. As the result, due to the operation of the parking brake, the mounting nut loosens, the parking brake pull-in is increased, and in the worst case the parking brake is ineffective.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
ABA-AWCHZ	Polo 1.0L	MY2018-2019	9,666
		Total	9,666