

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic / ~~Import Vehicles~~

CAMPAIGN No.	Gai-2800	DATE	2019/3/8
MANUFACTURE	MASSEY FERGUSON SA (Japanese Importer :MSK Farm Machinery Corporation CEO Zenta Ishikawa)		
DESCRIPTION OF DEFECT	In the crankshaft of the agricultural tractor, some of the torque of the front hub fixing bolt is insufficient because the management of the assembly tool is inappropriate. Therefore, the hub of the crankshaft idles in the crankshaft and the fan, water pump, alternator, front PTO may not be driven. In the worst case, the engine may overheat.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
YDS-SU66A2	MF7718-4CVT	2017	1
YDS-SU66A	MF7718-4D		1
		TOTAL	2