VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic / Import Vehicles

CAMPAIGN No.	Gai-2801	DATE	2018/3/8	
MANUFACTURE	MASSEY FERGUSON SA (Japanese Importer :MSK Farm Machinery Corporation			
	CEO Zenta Ishikawa)			
DESCRIPTION OF DEFECT	In the parking brake of the agricultural tractor, 1. Because the durability of the air hose is insufficient, cracks may occur in the air hose. Therefore, there is a danger that air may leak from the air hose and the parking brake may not be released.			
	2. Because the arrangement of the air tank pipes are inappropriate, water may accumulate in the pipes. Therefore, there is a danger that air is not supplied to the air cylinder and the parking brake will not be released.			

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
NO TYPE	F716VARIO T4	2012~2017	5
	F718VARIO T4	2012~2017	11
	F720VARIO T4	2012~2013	11
	F724VARIO T4	2012~2014	9
		TOTAL	36