

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic / Import Vehicles

CAMPAIGN No.	4463	DATE	Mar. 13. 2019
MANUFACTURER	Hino Motors, Ltd.		
DESCRIPTION OF DEFECT	On certain individual specification spare tire carriers for medium duty trucks, due to improper welding work, a crack may occur in the welding part. Therefore, the spare tire carrier may break by vibration etc. and fall off, resulting the spare tire carrier to block traffic.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
QKG-FE7JGAA	[HINO Ranger]	2015	9
		TOTAL	9