

Vehicle Safety/Pollution Recall Campaign in Japan

Import Vehicles

Campaign No.	Gai- 2798	Date	March. 15, 2019
Manufacturer	Jaguar Land Rover Limited (Japanese Importer : Jaguar Land Rover Japan Limited)		
Description of defect	2015, 2016 and 2017 Model Year Land Rover Discovery Sport vehicles fitted with a Takata manufactured non-desiccated ammonium nitrate inflator in the Driver's Airbag Module		

Type	Commercial name	Model year recalled	Number of vehicles
CBA-LC2A	「Discovery Sport」	2015 – 2017	1,159
Total			1,159