

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN NO.	4460	DATE	March. 19 . 2019
MANUFACTURER	NICHIGO CORPORATION		
DESCRIPTION OF DEFECT	<p>In the engine of the rotary snow plow, the gap between the cooling fan and the fan guard is inappropriate. When colliding with a street protrusion during snow removing work, the engine moves and the cooling fan and the fan guard contact each other. In the worst case, the cooling fan may be damaged and fall on the road.</p>		
TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
YDS-R03F	「HTR308A」	2018~2019 R03F-0002~ R03F-0078	56
TOTAL			56

【Notes】 The scope of the chassis number of the recalled vehicles, there is a case where the vehicle that do not qualify are also included.