

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic / Import Vehicles

CAMPAIGN No.	GAI-2806	DATE	22/03/2018
MANUFACTURE	McLaren (Japanese Importer : McLaren Automotive Asia Pte Ltd)		
DESCRIPTION OF DEFECT	Activation of a non-desiccated ammonium nitrate inflator with degraded propellant may result in an inflator rupture. An inflator rupture may cause metal fragments to pass through the air bag and into the vehicle interior at high speed on passenger side air bag.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
ABA-MP4-12CLT	「McLaren 675LT Coupe」	2016	38
ABA-MP4-12CLTS	「McLaren 675LT Spider」	2016	34
ABA-MP4-12CP	「McLaren 650S Coupe」	2015, 2016	39
ABA-MP4-12CSP	「McLaren 650S Spider」	2015, 2016	98

ABA-P13C	「McLaren 540C Coupe」	2016, 2017	87
ABA-P13GT	「McLaren 570GT」	2017	37
ABA-P13S	「McLaren 570S Coupe」	2016, 2017	89
ABA-P13SP	「McLaren 570S Spider」	2018	12
		TOTAL	434