

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic / Import Vehicles

CAMPAIGN No.	GAI-2815	DATE	March 25 ,2019
MANUFACTURE	JUNJIN HEAVY INDUSTRY CO.,LTD. (Japanese Importer : TOKYO CO.,LTD.)		
DESCRIPTION OF DEFECT	<p>This is a problem with the hydraulic pump PTO for concrete pump cars. Different products with insufficient strength were assembled to the bolt and nut that fasten the PTO flange to the propeller shaft. Therefore, there is a possibility that the bolt may be broken due to load and the like at the time of traveling and PTO drive. In addition, the propeller shaft may fall off and interfere with the safety of other traffic.</p>		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
QKG-PK39LD	Condor	2017	2
QPG-CY5YL	Quon	2017	2
QPG-CW5ZL	Quon	2016 – 2017	4
		TOTAL	8