

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	4465	DATE	Mar . 28 , 2019
MANUFACTURER	SUBARU CORPORATION		
DESCRIPTION OF DEFECT	Due to the improper prevention of moisture absorption into propellant for passenger-side airbag inflator, propellant could degrade under the cycle of temperature and humidity. As a result of propellant degradation, inflator housing may rupture during airbag deployment.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
DBA-YA5	「EXIGA」	2014 ~ 2015	157
DBA-YAM		2014 ~ 2016	8,885
CBA-GVB	「IMPREZA」	2014	397
CBA-GVF		2014	145
CBA-GRB		2014	171
CBA-GRF		2014	103
DBA-BM9	「LEGACY」	2014	225
DBA-BMG		2014	317
DBA-BMM		2014	1,475
DBA-BRF		2014	118
DBA-BRG		2014	1,030
DBA-BRM		2014	4,740
		TOTAL	17,763