

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Import Vehicles

CAMPAIN No.	Gai – 2813	DATE	29 March, 2019
MANUFACTURER	Dr. Ing. h.c. F. Porsche AG (Japanese Importer: Porsche Japan KK)		
DESCRIPTION OF DEFECT	There is a possibility that the side airbag sensors are not connected without play to the chassis due to high friction values when screwing them on. In the event of accidents in which the restraint systems are triggered, their full protective effect may be impaired as a result.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
ABA-982J1	718 Boxster	2018	6
	718 Cayman	2018	1
ABA-982J2	718 Boxster S	2018	2
	718 Boxster GTS	2018	1
	718 Cayman S	2018	1
ABA-911J1	911 Carrera	2018	8
	911 Carrera S	2018	4
	911 Carrera 4S	2018	1
	911 Carrera GTS	2018	4
	911 Targa 4	2018	3
	911 Targa 4S	2018	2
	911 Targa 4 GTS	2018	4
ABA-911J2	911 Turbo	2018	2
	911 Turbo S	2018	1
ABA-911J3	911 GT3	2018	4
-911J2-	911 Turbo S Exclusive	2018	2
		Total	46