

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Import Vehicles

CAMPAIGN No.	GAI-2824	Date	29.03.2019
MANUFACTURER	Volkswagen (Japanese Importer: Volkswagen Group Japan KK)		
DESCRIPTION OF DEFECT	Due to improper prevention for humidity control of Driver airbag inflator, propellant inside may suffer material wear under high humidity environment with temperature changing. As a result, container of the inflator may rupture when airbag deploy.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
ABA-3CCCZF	Passat Alltrack	2015	74
ABA-3CCDAC	CC 1.8T	2015-2016	155
ABA-5NCCZ	Tiguan 2.0T	2015-2016	260
DBA-3CCAX	Passat Sedan 1.4T	2015	45
DBA-5NCTH	Tiguan 1.4	2015-2016	800
DBA-7NCTH	Sharan 1.4 / 110kW	2015	1,327
DBA-AACHY	up! 1.0 / 55kW	2015-2016	6,774
DBA-AACHYW	cross up! 1.0 / 55kW	2016	673
		Total	10,108