

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	4472	DATE	Apr, 2, 2019
MANUFACTURER	KUBOTA Corporation		
DESCRIPTION OF DEFECT	At the clutch pedal return spring of the agricultural tractor, since the design is inappropriate, the hook portion of the spring may be broken. Therefore, the clutch of the driving system is always disengaged, there is a fear that the power of the driving system is cut off.		
TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
-	M7131	2015~2016	15
-	M7151	2015~2016	37
-	M7171	2015~2016	38
YDR-M7001	M7-131	2016~2017	38
	M7-151	2016~2017	96
	M7-171	2016~2017	49
-	M7-171	2016~2017	8
		TOTAL	281