

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	4476	DATE	Apr.4 2019
MUNUFACTURER	Mitsubishi Fuso Truck and Bus Corporation		
DESCRIPTION OF DEFECT	Since the size of the handle on the folding ramp installed at the center door of some buses is inappropriate, the handle may protrude when it is operated. There is a possibility that a passenger may trip over the handle and fall.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
QKG-MP38FK	「FUSO AERO STAR」	2017~2017	217
QKG-MP38FM		2017~2017	63
2KG-MP38FK		2017~2018	35
2KG-MP38FM		2017~2018	38
2PG-MP38FK		2017~2018	354
2PG-MP38FM		2017~2018	91
			TOTAL