

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	4477	DATE	Apr.4 2019
MUNUFACTURER	Mitsubishi Fuso Truck and Bus Corporation		
DESCRIPTION OF DEFECT	In the braking system of some rear tandem-axle drive heavy-duty trucks, the air pressure test connector for the braking system is assembled in a wrong position, due to inappropriate work instructions. When an air pressure test is performed, an incorrect value may be indicated, and the vehicle may not satisfy the technical requirements of the Regulation No. 13 (standards for the braking system).		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
2PG-FV74GZ	「FUSO SUPER GREAT」	2017~2018	16
2PG-FV74HZ		2017~2018	187
		TOTAL	203