

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Import Vehicles

CAMPAIGN No.	Gai-2822	DATE	April 9 th , 2019
MANUFACTURER	BMW (Japanese Importer: BMW Group Japan Corp.)		
DESCRIPTION OF DEFECT	<p>The diesel engine's fuel supply hose attached to the high-pressure fuel pump, the hose clamps may to rust because of insufficient corrosion prevention of the hose clamps.</p> <p>As a result, the hose clamps may crack and fuel may leak out of the hose.</p>		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
LDA-3D20	BMW 320d	2012 - 2014	15,124
		TOTAL	15,124