

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	4469	DATE	Apr.11, 2019
MANUFACTURER	SUBARU CORPORATION		
DESCRIPTION OF DEFECT	Due to inappropriate circuit structure on the combination meter, when the cabin is exposed to moisture for a long time and condensation occurs on the meter's circuit board, power circuit may have an electrical short. Therefore, smoke may be generated from the circuit, and in the worst case, it could lead to fire.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
GF-BE5	「LEGACY」	1998 ~ 2001	17,664
GF-BH5		1999 ~ 2001	15,517
		TOTAL	33,181