

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	4 4 8 1	DATE	April. 11. 2019
MANUFACTURER	N I S S A N		
DESCRIPTION OF DEFECT	<p>Regarding the front suspension, as the coil springs are unstable on the spring seat by the inappropriate spring shape. The coil springs change position on the spring seat while vehicle in motion and may contact with inside of spring seat. If the driver continue to drive in this condition, the coil spring coating may be worn down and rust may be created on spring. In worst case, the coil spring may be broken.</p>		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLES
DBA-E12	NOTE	2 0 1 2	5 0 0, 5 2 3
DBA-NE12		~	5 0, 4 9 4
DAA-HE12		2 0 1 9	1 8 5, 2 0 6
DAA-SNE12			9, 1 4 9
		TOTAL	7 4 5, 3 7 2