

VEHICLE SAFETY/ POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicle

CAMPAIGN No.	4483	DATE	April 11, 2019
MANUFACTURER	Komatsu Ltd.		
DESCRIPTION OF DEFECT	When hoses with fittings used for fuel tanks or hydraulic tanks were manufactured, they were inserted into the fittings by using wrong facilities, and the wires in some of them were damaged. As a result, those hoses may be damaged by the fuel or hydraulic oil pressure, and fuel or hydraulic oil may leak.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
YDP-WA138	「WA100-8」	2018-2019	34
YDR-WA137	「WA200-8」	2018-2019	26
YDR-WA136	「WA270-8」	2018	6
YDR-WA135	「WA320-8」	2018	5
YDS-WA130	「WA380-8」	2018	5
		TOTAL	76