

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic / Import Vehicles

CAMPAIGN No.	4473	DATE	April 12. 2019
MANUFACTURER	YANMAR AGRIBUSINESS CO.,LTD.		
DESCRIPTION OF DEFECT	In the lower guard of the agricultural tractor, since the mounting structure is inappropriate, the load from the front wheel may be repeatedly applied in the vertical direction, whereby the mounting bolt may be loosened. Therefore, if the use is continued as it is, the lower guard may fall.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE	
—	「YT330」	2016~2019	864	
—	「YT333」	2016~2019	1,639	
		2016~2019	220	
—	「YT338」	2016~2019	497	
		2016~2019	155	
—	「YT345」	2016~2019	1,198	
		2016~2019	244	
—	「YT352」	2016~2019	413	
—	「YT357」	2016~2019	2,033	
		2016~2019	515	
TOTAL			7,778	