

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic / Import Vehicles

CAMPAIGN No.	4474	DATE	April 12. 2019
MANUFACTURER	YANMAR AGRIBUSINESS CO.,LTD.		
DESCRIPTION OF DEFECT	In the fuel tank cover of agricultural combine harvester, the cover contacts with the fuel hose if assembly direction is incorrect. Therefore, if the fuel hose is used as it is, the fuel hose may be cracked due to vibration, and in the worst case, the fuel may leak.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
-	「 YH6115 」	2018	1
TOTAL			1