

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Import Vehicles

CAMPAIGN No.	GAI-2818	DATE	Apr. 17, 2019
MANUFACTURER	Audi (Japanese Importer: Audi Japan KK)		
DESCRIPTION OF DEFECT	It is possible that fuel may escape from one or both fuel rails. As a result, there may be a smell of fuel. The fuel rails of both cylinder banks must be replaced.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
ABA-4GCREB	Audi A6 Allroad	2016-2017	285
ABA-4GCREC	Audi A7 SB 3.0Tq	2016-2017	590
ABA-4GCRES	Audi A6 3.0Tq / Audi A6 Avant 3.0Tq	2016-2017	192
ABA-4MCREA	Audi Q7 3.0Tq Air sus	2016-2017	593
ABA-4MCRES	Audi Q7 3.0Tq	2016-2017	88
ABA-8FCREF	Audi S5 Cabriolet	2015-2017	41
ABA-8KCREF	Audi S4/ Audi S4 Avant	2015	235
ABA-8TCREF	Audi S5	2015-2016	45
ABA-8TCREL	Audi S5 SB	2015-2016	202
DBA-4HCREF	Audi A8 3.0Tq	2014-2017	295
		Total	2,566