

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic ☒ Import Vehicles

Campaign No.	4478	Date	April 18., 2019
Manufacture	CATERPILLAR JAPAN LLC.		
Description of Deffect	A main power relay may have an internal short circuit due to material migration. Once the defect appears, machine control will be lost immediately or termal incident occurs.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
KDP-SAT	「910H」	2011-2014	1196
JDS-MCC	「938H」	2011-2013	88
JDS-J5J	「950H」	2011-2013	93
JDS-J6J	「962H」	2012-2013	15
JDS-A6J	「966H」	2011-2913	21
JDS-A7J	「972H」	2012	3
JDS-A8J	「980H」	2011	1
		TOTAL	1,417