

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic / Import Vehicles

CAMPAIGN No.	4 4 9 4	DATE	A p r . 2 2 . 2 0 1 9
MANUFACTURER	YAMAHA MOTOR CO., LTD.		
DESCRIPTION OF DEFECT	In the manufacturing process of the front wheel brake lever, because of an inappropriate handling of the discarded parts (due to insufficient strength), the discarded parts may have been mixed in with the regular standard parts and assembled to vehicles. Because of that, the said brake lever may break while operating the brake lever, and as a result, it will be impossible to operate the brake.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
2 B K - R G 4 3 J	YZF-R25	2 0 1 9	2 5
	YZF-R25A	2 0 1 9	1 3
	MT250	2 0 1 9	1
		TOTAL	3 9