

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Import Vehicles

| | | | |
|-----------------------|---|------|---------------|
| CAMPAIGN No. | GAI-2833 | DATE | Apr. 23, 2019 |
| MANUFACTURER | Audi (Japanese Importer: Audi Japan KK) | | |
| DESCRIPTION OF DEFECT | <p>The car with TAKATA driver airbag, it is possible that the gas generator housing may be damaged if the driver airbag is deployed. As a result, metal pieces of the gas generator can shoot into the passenger compartment and injure or kill the occupants.</p> <p>The airbag unit for the driver airbag must be replaced.</p> | | |

| TYPE | COMMERCIAL NAME | MODEL YEAR RECALLED | NUMBER OF VEHICLE |
|------------|------------------|---------------------|-------------------|
| ABA-4SCSPD | Audi R8 V10 plus | 2016 – 2017 | 64 |
| ABA-4SCSPF | Audi R8 V10 | 2016 – 2017 | 58 |
| ABA-FVCHH | Audi TT 2.0T | 2016 – 2017 | 1,255 |
| ABA-FVCHHF | Audi TT 2.0Tq | 2016 – 2017 | 2,032 |
| ABA-FVCJS | Audi TT 1.8T | 2016 – 2017 | 889 |
| ABA-FVCJXF | Audi TTS | 2016 – 2017 | 737 |
| | | Total | 5,035 |