

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic / ~~Import Vehicles~~

CAMPAIGN No.	Gai-2831	DATE	2019/4/24
MANUFACTURE	MASSEY FERGUSON SA (Japanese Importer :MSK Farm Machinery Corporation CEO Zenta Ishikawa)		
DESCRIPTION OF DEFECT	In the intake socket of the agricultural tractor, so the shape of the intake socket is inappropriate, the intake socket may contact with the radiator. Therefore, there is a danger that coolant may leak from the radiator.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
NO TYPE	F927VARIO S4	2016	1
	F930VARIO S4	2015~2017	3
	F933VARIO S4	2015~2017	7
	F936VARIO S4	2015~2017	15
	F939VARIO S4	2015~2018	9
		TOTAL	35