VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Import Vehicles

CAMPAIGN No.	Gai-2835	DATE	2019/4/24		
MANUFACTURE	Daimler AG				
	(Japanese Importer : Mercedes-Benz Japan Co,. Ltd.)				
DESCRIPTION OF DEFECT	On certain Right-Hand Drive E-Class vehicles (213 platform) the assembly process of the air condition unit might not have been carried out according to production specification. Thus, the air condition unit might have collided with the airbag control unit during assembly. As a result the airbag control unit might have been damaged. This might lead to an impairment of the airbag control unit functionality. In this case, a false activation of the airbags cannot be excluded. This would increase the risk of injury for the passengers as well as the risk of a crash.				

TYPE	COMMERCIAL	MODEL YEAR	NUMBER OF
	NAME	RECALLED	VEHICLE
RBA-213042C	E200	2017	1386
DBA-213043C	E200 4MATIC		36
LDA-213004C	E220d		293
RBA-213045C	E250		365
RBA-213071	E400 4MATIC		86
		TOTAL	2166