

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic ~~Import Vehicles~~

CAMPAIGN No.	Gai-2836	DATE	2019/4/24
MANUFACTURE	Daimler AG (Japanese Importer : Mercedes-Benz Japan Co., Ltd.)		
DESCRIPTION OF DEFECT	On certain C-Class (platform 205), E-Class (platform 213), and S-Class (platform 222) vehicles a reset in the CPC control unit could occur while driving due to a software error. This could result in various consequences. Fault codes of the current driving cycle might not be stored in the control unit as legally required. If the reset occurs during ECO Stop the engine would not restart automatically. In addition vehicles equipped with engine types M256/ M264/ M276/ M274 could coast due to engine stalling. In this case the engine can be restarted while coasting.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
DBA-205040C	C180	2019	2
5AA-205277	C200 Station Wagon		1
DBA-213068	E450 4MATIC		1
DBA-213268	E450 4MATIC Station Wagon		1
DAA-222058	S450	2018	487
DAA-222158			22
		TOTAL	514