VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

			Domestic Import Vehicles	
CAMPAIGN No.	Gai-2839	DATE	2019/4/24	
MANUFACTURE	Daimler AG			
	(Japanese Importer : Mercedes-Benz Japan Co,. Ltd.)			
DESCRIPTION OF DEFECT	On certain A-Class vehicles (177 platforms), the driver might temporarily not be able to deactivate the high beam with the high beam lever. This might only occur if the adaptive high-beam-assist had been automatically deactivated as specified (e.g. due to dirt on the multi-purpose camera), and the high beam had subsequently been manually re-activated by the driver. The high beam can, however, still be deactivated at all times by turning the light switch to "manual light". In this case, glare to oncoming traffic cannot be ruled out, increasing the risk of a crash. In addition, legal requirements might not be met.			

TYPE	COMMERCIAL	MODEL YEAR	NUMBER OF
	NAME	RECALLED	VEHICLE
5BA-177084	A180	2019	2
		TOTAL	2