

VEHICLE SAFETY/ POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicle

CAMPAIGN No.	4493	DATE	April 26, 2019
MANUFACTURER	Komatsu Ltd.		
DESCRIPTION OF DEFECT	In the engine for wheel loaders, the minimum clearance of the partition between the radiator and engine to the aftercooler hose passing through the partition was insufficiently evaluated, and the minimum clearance of the partition to the aftercooler hose was insufficient in some machines. In those machines, the aftercooler hose interferes with the partition due to vibration of the engine, etc. If they used as they are, the aftercooler hose may crack. In the worst case, intake air may leak, and black smoke may occur because of defective combustion.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
WDP-WA124	「WA100-7」	2013-2017	3841
		TOTAL	3841