

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Import Vehicles

CAMPAIGN NO.	4501	DATE	May 16 ,2019
MANUFACTURER		ISUZU MOTORS LIMITED	
DESCRIPTION OF DEFECT		On certain emission control devices of heavy-duty sightseeing buses, due to the improper wiring instructions for NOx sensor, upstream and downstream NOx sensor are connected in reverse order. Therefore, the emission control device may not function correctly, resulting emission gas not to satisfy safety regulations.	

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
2DG-RU2AHDJ 2KG-RU2AHDJ	[ISUZU GALA]	2017-2019	147
TOTAL			147