

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Import Vehicles

CAMPAIGN No.	Gai-2845	DATE	May 21 th , 2019
MANUFACTURER	BMW (Japanese Importer: BMW Group Japan Corp.)		
DESCRIPTION OF DEFECT	On the front axle components, the durability of the swivel bearing is improper due to the material selection and dimensional design. Therefore, the vehicle vibration may cause a crack in the clamp of the swivel bearing for fixing the shock absorber (strut), which may cause abnormal noise.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
CBA-3C30	BMW M4	2017	25
TOTAL			25