

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Import Vehicles

CAMPAIGN No.	Gai-2846	DATE	May 21 th , 2019
MANUFACTURER	BMW (Japanese Importer: BMW Group Japan Corp.)		
DESCRIPTION OF DEFECT	In the powertrain device, the durability of the propeller shaft is insufficient because the shape of the connecting inadequate. For this reason, the connection can get detached, and the propeller shaft cannot transmit power to the rear axle.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
CBA-3C30	BMW M3	2016	91
	BMW M4	2016	141
TOTAL			232