

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

~~Domestic~~ /Import Vehicles

CAMPAIGN No.	Gai-2851	DATE	22/May/2019
MANUFACTURER	Automobiles Volvo Car Corporation (Japanese Importer: Volvo Car Japan Limited)		
DESCRIPTION OF DEFECT	This condition will render a coolant leakage and also pose a risk for coolant leakage on the catalytic converter. If the coolant leakage goes unnoticed, in the worst case scenario, result in a fire in the engine bay area when the vehicle is stationary. The corrective action is to Replace the bleeder hose.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
VOLVO	[ XC90]	2016	318
TOTAL			318