

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	4 5 0 3	DATE	May. 23. 2019
MANUFACTURER	N I S S A N		
DESCRIPTION OF DEFECT	Regarding the ABS actuator, due to insufficient corrosion resistance for the brake fluid with unstable property such as the unspecified brake fluid, gelatinous material is generated on zinc coating of the valve surface and then the valve sliding may become worse. Therefore, if the valve is not closed correctly, brake pedal travel is increased by low fluid pressure and stopping distance may be increased.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLES
CBA-TZ51	MURANO	2 0 0 8	6, 408
CBA-TNZ51		~	8, 869
CBA-PNZ51		2 0 1 5	3, 077
DBA-TE52	E L G L A N D		43, 439
DBA-TNE52			9, 649
DBA-PE52			12, 083
DBA-PNE52			6, 697
		TOTAL	90, 222