

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic / Import Vehicles

CAMPAIGN No.	Gai-2855	DATE	May 23, 2019	
MANUFACTURER	Volvo Truck Corporation (Japanese Importer : UD Trucks Corporation)			
DESCRIPTION OF DEFECT	With regards to the Advanced Emergency Braking System (AEBS) for heavy-duty tractors, due to inappropriate program for the Lane Position Object Sensor (LPOS), when the vehicle turns at very low speed and drives straight, the sensing function of the Forward Looking Sensor (FLS) and the Lane Position Object Sensor (LPOS) camera may become deteriorated, which may cause unexpected brakings. Thus, the vehicle may not conform with the Japan Safety Regulations Article 12 (Braking system standard) requirements.			
TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE	
FH	2DG-KA2TDA1	2018	36	
	2DG-KA2TEA1	2018-2019	68	
	2DG-KA2TEF1	2018-2019	3	
	2DG-KA4TBA1	2018-2019	28	
	2DG-KA4TCA1	2019	4	
		TOTAL	139	